

557619

SDMS DocID



Site Name: Covitch Property / Former ATF Davidson Co.

Location: Northbridge, MA

Photo: 4-1

CERCLIS No.: MAD046128559

TDD No.: 95-07-0065

Photographer: M. Jennings

Date: 2 May 1996

Time: 1230

Description: LD = East; six 55-gallon metal drums located at Swissturn, 1st floor, Building No. 4 (cutting oils with additional unknown contents).



35
11
13

Site Name: Covitch Property / Former ATF Davidson Co.

Location: Northbridge, MA

Photo: 4-2

CERCLIS No.: MAD046128559

TDD No.: 95-07-0065

Photographer: M. Jennings

Date: 2 May 1996

Time: 1232

Description: LD = East; solvent parts wash sink at Swissturn,
located in Building No. 4.

11
13



3
0
1
2

Site Name: Covitch Property / Former ATF Davidson Co.

Location: Northbridge, MA

Photo: 4-3

CERCLIS No.: MAD046128559

TDD No.: 95-07-0065

Photographer: M. Jennings

Date: 2 May 1996

Time: 1233

Description: LD = North; various containers of material, including cutting oil mixtures, and metal turnings, located in Building No. 4, at Swissturn. Note: Oil stained flooring.

1
2



0112

Site Name: Covitch Property / Former ATF Davidson Co.

Location: Northbridge, MA

Photo: 4-4

CERCLIS No.: MAD046128559

TDD No.: 95-07-0065

Photographer: M. Jennings

Date: 2 May 1996

Time: 1235

Description: LD = East; various containers of different type metal turnings located in Building No. 4, at Swissturn.

0112



COLD ROLL

SHINNISS
STEEL

STAINLESS
STEEL
ONLY

WALL
MATERIAL

14

Site Name: Covitch Property / Former ATF Davidson Co.

Location: Northbridge, MA

Photo: 4-5

CERCLIS No.: MAD046128559

TDD No.: 95-07-0065

Photographer: M. Jennings

Date: 2 May 1996

Time: 1240

Description: LD = East; oil soaked with absorbent material located in basement of Building No. 4, beneath Swissturn.



RIT

Site Name: Covitch Property / Former ATF Davidson Co.

Location: Northbridge, MA

Photo: 4-6

CERCLIS No.: MAD046128559

TDD No.: 95-07-0065

Photographer: M. Jennings

Date: 2 May 1996

Time: 1241

Description: LD = East; oily material leaking through ceiling boards Building No. 4, beneath Swissturn (basement).

RIT



Site Name: Covitch Property / Former ATF Davidson Co.

Location: Northbridge, MA

Photo: 4-7

CERCLIS No.: MAD046128559

TDD No.: 95-07-0065

Photographer: M. Jennings

Date: 2 May 1996

Time: 1243

Description: LD = East; oil puddle on floor of basement below
Swissturn, Building No. 4. (Directly below photograph No. 4-6).



Site Name: Covitch Property / Former ATF Davidson Co.

Location: Northbridge, MA

Photo: 4-8

CERCLIS No.: MAD046128559


TDD No.: 95-07-0065

Photographer: M. Jennings

Date: 2 May 1996

Time: 1315

Description: LD = West; interior of Covitch Raceway, Building No. 19 (former Powerhouse).



22
21
20
19
18
17
16
15
14
13
12
11
10
9
8
7
6
5
4
3
2
1

Site Name: Covitch Property / Former ATF Davidson Co.

Location: Northbridge, MA

Photo: 4-9

CERCLIS No.: MAD046128559

TDD No.: 95-07-0065

Photographer: M. Jennings

Date: 2 May 1996

Time: 1315

Description: LD = West; interior of Covitch Raceway, Building No. 19 (former Powerhouse).

1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22



2113

Site Name: Covitch Property / Former ATF Davidson Co.

Location: Northbridge, MA

Photo: 4-10

CERCLIS No.: MAD046128559

TDD No.: 95-07-0065

Photographer: M. Jennings

Date: 2 May 1996

Time: 1330

Description: LD = East; five metal 55-gallon drums of gear lubricant at Commtran, second floor, Building No. 4. Note: Catch pan.

2113



23

Site Name: Covitch Property / Former ATF Davidson Co.

Location: Northbridge, MA

Photo: 4-11

CERCLIS No.: MAD046128559

TDD No.: 95-07-0065

Photographer: M. Jennings


Date: 2 May 1996

Time: 1332

Description: LD = South; five metal 55-gallon drums of drawing compound located at Commtran, second floor, in Building No. 4.

Note: Stained flooring and absorbent material.

4-11-96



2

Site Name: Covitch Property / Former ATF Davidson Co.

Location: Northbridge, MA

Photo: 4-12

CERCLIS No.: MAD046128559

TDD No.: 95-07-0065

Photographer: M. Jennings

Date: 2 May 1996

Time: 1335

Description: LD = West; one metal 55-gallon drum labeled "regulated recyclable material," (contents unknown); also note stained concrete flooring and plastic jug to catch oil drips; Commtran, 2nd floor, Building No. 9.

2
1
B



Site Name: Covitch Property / Former ATF Davidson Co.

Location: Northbridge, MA

Photo: 4-13

CERCLIS No.: MAD046128559

TDD No.: 95-07-0065

Photographer: M. Jennings

Date: 2 May 1996

Time: 1400

Description: LD = North; one metal 55-gallon drum labeled hazardous waste (plasticizer), located at Alan Bailey Tag & Label Co. in Building No. 11.



HAZARDOUS WASTE

ANCHOR

Anchor Building North • Orange Park, FL 32073
Anchor Building South • Santa Fe Springs, CA 90670

FOR INDUSTRIAL USE ONLY

55 GALLONS (208.17 LITERS)

23
5:
1

Site Name: Covitch Property / Former ATF Davidson Co.

Location: Northbridge, MA

Photo: 4-14

CERCLIS No.: MAD046128559

TDD No.: 95-07-0065

Photographer: M. Jennings

Date: 2 May 1996

Time: 1410

Description: LD = West; five metal 55-gallon drums of hazardous material (plasticizer) located at Alan Bailey Tag & Label Co. in Building No. 11. No floor staining observed.

1-1-1
1-1-1
1-1-1



Site Name: Covitch Property / Former ATF Davidson Co.

Location: Northbridge, MA

Photo: 4-15

CERCLIS No.: MAD046128559

TDD No.: 95-07-0065

Photographer: M. Jennings

Date: 2 May 1996

Time: 1412

Description: LD = Southwest; seven metal 55-gallon drums (2 plasticizers, 5 of unknown contents) located at Alan Bailey Tag & Label Co. in Building No. 11.



Site Name: Covitch Property / Former ATF Davidson Co.

Location: Northbridge, MA

Photo: 4-16

CERCLIS No.: MAD046128559

TDD No.: 95-07-0065

Photographer: M. Jennings

Date: 2 May 1996

Time: 1412

Description: LD = Northeast; five metal 55-gallon drums located at Alan Bailey Tag & Label Co. in Building No. 11 (same subject as photos No. 4-14 with different LD).



R17

Site Name: Covitch Property / Former ATF Davidson Co.

Location: Northbridge, MA

Photo: 4-17

CERCLIS No.: MAD046128559

TDD No.: 95-07-0065

Photographer: M. Jennings

Date: 2 May 1996

Time: 1417

Description: LD = North; various containers of naphtha solvents located as Tomkins Corp., first floor, Building No. 12. Note:
Peeling labels and stained concrete flooring.

1112



Site Name: Covitch Property / Former ATF Davidson Co.

Location: Northbridge, MA

Photo: 4-18

CERCLIS No.: MAD046128559

TDD No.: 95-07-0065

Photographer: M. Jennings

Date: 2 May 1996

Time: 1419

Description: LD = West; various containers of oil material, note stained concrete flooring and absorbent material present. Materials located at Tomkin Corporation, 1st floor, Building No. 12.
[Composite 1 of 3 (4-13 through 4-20)]



211

Site Name: Covitch Property / Former ATF Davidson Co.

Location: Northbridge, MA

Photo: 4-19

CERCLIS No.: MAD046128559

TDD No.: 95-07-0065

Photographer: M. Jennings

Date: 2 May 1996

Time: 1419

Description: LD = West; various containers of oil material, note stained concrete flooring and absorbent material present. Materials located at Tomkin Corporation, 1st floor, Building No. 12.
[Composite 2 of 3 (4-13 through 4-20)]

211



Site Name: Covitch Property / Former ATF Davidson Co.

Location: Northbridge, MA

Photo: 4-20

CERCLIS No.: MAD046128559

TDD No.: 95-07-0065


Photographer: M. Jennings

Date: 2 May 1996

Time: 1419

Description: LD = West; various containers of oil material, note stained concrete flooring and absorbent material present. Materials located at Tomkin Corporation, 1st floor, Building No. 12.

[Composite 3 of 3 (4-13 through 4-20)]



4-22

Site Name: Covitch Property / Former ATF Davidson Co.

Location: Northbridge, MA

Photo: 4-22

CERCLIS No.: MAD046128559

TDD No.: 95-07-0065

Photographer: M. Jennings

Date: 2 May 1996

Time: 1424

Description: LD = West; 28 metal 55-gallon drums of "waste oils" and 1 fiberboard drum of unknown material at Tomkins Corp., 1st floor, in Building No. 12. [Composite 2 of 2 (4-21 through 4-22)]

4-22



Site Name: Covitch Property / Former ATF Davidson Co.

Location: Northbridge, MA

Photo: 4-21

CERCLIS No.: MAD046128559

TDD No.: 95-07-0065

Photographer: M. Jennings

Date: 2 May 1996

Time: 1424

Description: LD = West; 28 metal 55-gallon drums of "waste oils" and 1 fiberboard drum of unknown material at Tomkins Corp., 1st floor, in Building No. 12. [Composite 1 of 2 (4-21 through 4-22)]



FOI:

Site Name: Covitch Property / Former ATF Davidson Co.

Location: Northbridge, MA

Photo: 4-23

CERCLIS No.: MAD046128559

TDD No.: 95-07-0065

Photographer: M. Jennings

Date: 2 May 1996

Time: 1440

Description: LD = North; numerous containers of printing ink and flammable material located at Classic Envelope, second floor, Building No. 10. Note: Staining and storage techniques.

012

ABLE FLAMMABLE
RE AWAY KEEP FIRE AWAY

FLAMMABLE FLAMMABLE
KEEP FIRE AWAY KEEP FIRE AWAY

